

6951 Westminster Highway, Richmond, BC
Mailing Address: PO Box 5350, Vancouver BC, V6B 5L5
Telephone 604 276-3100 Toll Free 1-888-621-7233 Fax 604 276-3247

The *Workers Compensation Act* requires that the employer must post a copy of this report in a conspicuous place at or near the workplace inspected for at least seven days, or until compliance has been achieved, whichever is the longer period. A copy of this report must also be given to the joint committee or worker health and safety representative, as applicable.

Inspection Report #201517769044B

Employer Name	Jobsite Inspected	Scope of Inspection
RIO TINTO ALCAN INC.	Kitimat Works - Smelter 1 Smeltersite Road Kitimat BC V8C 2H2	C-Casting

Date of Initiating Inspection	Date of This Inspection	Delivery Date of This Report	Delivery Method
Nov 05, 2015	Nov 12, 2015	Nov 12, 2015	Email

THERE ARE ZERO (0) ORDERS OUTSTANDING

ACTION MAY STILL BE NECESSARY TO ENSURE COMPLIANCE PLEASE READ FULL REPORT

Summary of Orders

See "Orders – Full Details" section of this Inspection Report for orders cited

Order No.1 <input checked="" type="checkbox"/>	Status: Complied	Cited: OHS5.10(1)
------------------------------------------------	-------------------------	--------------------------

ORDER STATUS LEGEND

Order Status	Description
Outstanding	Order Outstanding - Action Required to Achieve Compliance
Complied	Compliance Achieved - No Further Action Required
Closed	Order Could Not be Followed Up – No Further Action Required
Rescinded	Order has been cancelled – No Further Action Required

INSPECTION NOTES

This follow-up inspection report is for administrative purposes to authenticate appropriate compliance with the order noted and to document receipt of the Employer's written Notice of Compliance (NOC) for IR201517769044A issued on November 6, 2015. The employer's written response, dated November 10, 2015, has been accepted as compliance for the order.

A copy of this inspection report will be mailed to the head office address of the employer from Prevention Records, Richmond.

No response is required upon receipt of this report.

Please do not hesitate to contact me should you have any questions or concerns regarding this inspection report.

Erin Guy, M.Sc (A) | Occupational Hygiene Officer
WorkSafeBC
4450 Lakelse Avenue | Terrace, BC V8G 1P2
250-615-6640 | 1-800-663-3871 | 250-615-6633 (fax)
Erin.Guy@WorkSafeBC.com

This was a follow-up inspection to authenticate appropriate compliance with the order(s) noted.

ORDERS

An employer who fails to comply with Part 3 of the *Workers Compensation Act*, the *Occupational Health & Safety Regulation*, or WorkSafeBC orders may be subject to monetary or other sanctions as prescribed by the *Workers Compensation Act*.

Orders - Full DetailsOrder No.1 Status: **Complied**Cited: **OHS5.10(1)****Progress towards compliance:**

Nov 12, 2015 - The employer's written response for this order, received on November 10, 2015, stated that workplace labels were applied to all product bins containing VANSIL W-30 on November 6, 2015. Based upon the actions taken to comply which are described in the submitted Notice of Compliance report, this order has been complied with.

Initiating order:

VANSIL W-30 (Wollastonite), manufactured by Vanderbilt Minerals, LLC, is poured from original supplier bags into metal storage bins for operators to use as trough gate sealant on an as-needed basis. This product is a hazardous product, containing quartz and the metal storage bins do not have a workplace label applied to them.

This is in contravention of the Occupational Health and Safety Regulation Section 5.10(1).

If a hazardous product in a workplace is in a container other than the container in which it was received from a supplier, the employer must ensure that the container has a workplace label applied to it.

Measures to Ensure Compliance:

Without undue delay, the employer must ensure a workplace label is applied to all metal storage bins which contain decanted VANSIL W-30 product. Workplace labels require the product name (matching the safety data sheet product name), safe handling procedures (may include pictograms or other supplier label information), and reference to the safety data sheet.

Pursuant to section 194 (1) of the Workers Compensation Act, the employer must prepare a Notice of Compliance report. In accordance with section 194 (2), this report must detail what has been done to comply with the order, and where compliance has not been achieved by the time the report has been submitted, include a plan of what will be done to comply and when compliance will be achieved. Please submit the report no later than **December 7, 2015**.

6951 Westminster Highway, Richmond, BC
 Mailing Address: PO Box 5350, Vancouver BC, V6B 5L5
 Telephone 604 276-3100 Toll Free 1-888-621-7233 Fax 604 276-3247

Employer #	Mailing Address	Classification Unit #	Operating Location
54363	ATTN: PAYROLL 1188 SHERBROOKE W MONTREAL QC H3A 3G2	712035	002

Lab Samples Taken	Direct Readings	Results Presented	Sampling Inspection(s)
N	N	N	

Workers onsite during Inspection	Notice of Project Number
12	

Inspection Report Delivered To	Employer Representative Present During Inspection	Worker Representative Present During Inspection	Labour Organization & Local
Sylvie Stekelenburg	Not Applicable	Not Applicable	Not Applicable

WorkSafeBC Officer Conducting Inspection
Erin Guy

*Inspection Time	*Travel Time
0.75 hrs	0.00 hrs

*The time recorded above reflects the inspection time and travel time associated with this inspection report and includes time spent on pre and post-inspection activities. Additional time may be added for subsequent activity.

Right to a Review of Orders

Any employer, worker, owner, supplier, union, or a member of a deceased worker's family directly affected may, within 45 calendar days of the delivery date of this report, in writing, request the Review Division of WorkSafeBC to conduct a review of an order, or the non-issuance of an order, in this report by contacting the Review Division. Employers requiring assistance may contact the Employers' Advisers at 1-800-925-2233.

WorkSafeBC values your feedback. To obtain that feedback, an external market research provider may be contacting you to complete a survey.